

Reduce Your Risk Factors

Risk Factor:

Burning Plastics that produces thick black smoke full of carbon monoxide and other toxic polymers.

Risk Factor:

Heavy metals like hexavalent chromium, lead, and other toxins that cling to the skin.

Risk Factor:

Dirt and grime that contain potentially cancer-causing elements.

Risk Factor:

Carcinogens like Acrolein, Formaldehyde, and Benzene.



on-scene decon cloths





Feel the Difference

www.bullard.com/deconcloths



on-scene decon cloths

Experience Protection



The Bullard Difference:

Helps to remove soot, grime, plastics, toxins, and heavy metal particles that traditional wipes often miss

- Does not contain phosphates or chelating agents
- Extra-large (10"x15") cloth helps firefighters and first responders reduce toxins for an all over body clean
- Cloths are biodegradable, paraben free, latex free, and alcohol free
- Contains no aloe or skin softeners

Made in
the USA 



We proudly support the Firefighter Cancer Support Network with a portion of the proceeds from every Decon Cloths purchase.

www.firefightercancersupport.org

www.bullard.com/deconcloths

©2023 Bullard. All rights reserved.
8268 (0323)